

DAMAGE CHART

A/C Reg: T-A321C

Type: A321i

A/C S/N: 0123456

Effective date: 04-Jun-2025 / 07:21 UTC

Table of Contents

Discrepancies not included on aircraft pictures

Fuselage Sections

Wings

Stabilisers

#1 Engine

#2 Engine

Floors

Cargo doors

EXAMPLE

	DAMAGE CHART A321i EFFECTIVE DATE - 04/06/2025	A/C REG: T-A321C A/C S/N: 0123456 
---	--	---


Repair and damage labels on diagrams in the report

Each **repair** record is displayed with a reference number in a circle which is connected to the repair location on the aircraft.

Each **damage** record is displayed with a reference number in a square which is connected to the damage location on the aircraft.

EXAMPLE


Fuselage Sections



Front LH

No	Type	Location	Description	Date
T-143*	Damage	FR21 + 131.00mm, STRG23LH + 60.00mm	Dent aft of pax door 1	09/09/2024
T-174*	Damage	Cockpit Window	Scratch	19/11/2024
T-196*	Damage	FR21 + 145.00mm, STRG24LH + 49.00mm	Dent near pax door	09/02/2025
T-219*	Damage	FR13 + 125.00mm, STRG17LH + 88.00mm	Dent near pax door	08/04/2025
T-220*	Damage	FR21 + 112.00mm, STRG11LH + 123.00mm	Dent on fwd fuse	08/04/2025
T-221*	Damage	FR21 + 174.00mm, STRG18LH + 145.00mm	Dent near fwd door	08/04/2025
11	Repair	FR23 + 50.00mm, STRG13LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR23 STRG13	08/09/2017
15	Damage	FR20 + 50.00mm, STRG20LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR20 STRG20	27/02/2018
24	Damage	FR21 + 50.00mm, STRG9LH + 10.00mm	Gouge on Fuselage - Section 15/21 LH FR21 STRG9	27/02/2018
25	Damage	FR23 + 287.00mm, STRG37LH + 65.00mm	Dent and Gouge on Fuselage - Section 15/21 FR23 STRG37	01/04/2018
46	Damage	FR1 + 266.00mm, CLLH + 969.00mm	Dent on Fuselage - Section 15/21 FR1 STRG20	14/01/2022
76	Repair	FR14 + 228.00mm, STRG22LH + 75.00mm	Corrosion on Fuselage - Section 11/12 LH FR14 STRG16	18/11/2022
77	Damage	FR18 + 50.00mm, STRG23LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR18 STRG23	19/11/2022
83	Damage	PASSENGER DOOR NO 1 LH	Scratch on PASSENGER DOOR NO 1 LH	25/11/2022

84	Damage	FR20 + 50.00mm, STRG23LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR20 STRG23	26/11/2022
96	Repair	FR12 + 50.00mm, STRG23LH + 10.00mm	sheared Fateners on Fuselage - Section 11/12 LH FR12 STRG23	08/12/2022
107	Damage	FR14 + 10.00mm, STRG18LH + 5.00mm	Dent fwd lh door 1	11/01/2024
126	Damage	Door - Avionics Compartment Lateral Left	ligghtning strike	17/04/2024
129	Damage	FR19 + 64.00mm, STRG24LH + 53.00mm	Dent below pax door	15/05/2024
141	Damage	FR21 + 80.00mm, STRG18LH + 10.00mm	Dent aft pax door	30/06/2024
144	Damage	FR25 + 300.00mm, STRG21LH + 30.00mm	Dent close to aoa sensor	16/09/2024
146	Damage	FR24 + 200.00mm, STRG26LH + 70.00mm	Scratch near sensor on lh side	17/09/2024
150	Damage	FR20 + 250.00mm, STRG22LH + 100.00mm	Dent aft of fwd pax door	09/10/2024
172	Damage	FR14 + 100.00mm, STRG20LH + 10.00mm	2 dents fwd of pax door	19/11/2024
175	Damage	FR33 + 59.00mm, STRG23LH + 91.00mm	Dents near middle pax door	02/12/2024
192	Damage	FR23 + 50.00mm, STRG29LH + 20.00mm	Dent near aoa probe	17/12/2024
193	Damage	FR24 + 50.00mm, STRG28LH + 10.00mm	Strike near aoa probe	17/12/2024
194	Damage	FR25 + 180.00mm, STRG24LH + 70.00mm	Dents below aoa sensor	21/01/2025
215	Damage	FR19 + 100.00mm, STRG24LH + 40.00mm	Dent below fwd pax door	04/03/2025
216	Damage	FR17 + 120.00mm, STRG24LH + 90.00mm	Dent below fwd pax door	05/03/2025
217	Damage	FR23 + 200.00mm, STRG19LH + 50.00mm	Strike aft of fwd door	10/03/2025
227	Damage	FR17 + 150.00mm, STRG24LH + 100.00mm	Dent below fwd pax door	15/04/2025
228	Damage	FR20 + 200.00mm, STRG21LH + 70.00mm	Dent aft lower fwd pax door	16/04/2025
229	Damage	FR26 + 10.00mm, STRG24LH - 10.00mm	Dent	12/05/2025
230	Damage	FR26 + 100.00mm, STRG20LH + 50.00mm	Dent near aoa sensor	20/05/2025




Front RH

No	Type	Location	Description	Date
T-98*	Damage	FR23 + 280.00mm, STRG18RH + 55.00mm	Dent - Fuse Skin, AFT of R1 Door, FWD of Triangle Reference Point, FR 23 -24, S18R-S19R	26/09/2023
T-136*	Damage	FR28 + 178.00mm, STRG27RH + 69.00mm	Dent	02/06/2024
T-148*	Damage	FR28 + 373.00mm, STRG30RH + 61.00mm	2 Dents near CGO door	08/10/2024
T-197*	Damage	FR34 + 90.00mm, STRG12RH + 23.00mm		09/02/2025
T-199*	Damage	FR31 + 243.00mm, STRG21RH + 20.00mm	Dent	09/02/2025
T-218*	Damage	FR14 + 83.00mm, STRG19RH + 92.00mm		23/10/2024
1	Repair	FR11 + 137.00mm, STRG32RH + 173.00mm	Skin/Fastener Burn on Fuselage - Section 15/21 RH FR10 STRG32	09/01/2012
2	Repair	FR27 + 269.00mm, STRG2RH + 137.00mm	Skin/Fastener Burn on Fuselage - Section 15/21 RH FR26 STRG33	27/04/2015
44	Damage	FR29 + 50.00mm, STRG27RH + 10.00mm	Dent on Fuselage - Section 15/21 RH FR29 STRG27	20/11/2021
100	Damage	FR23 + 311.00mm, STRG24RH + 52.00mm	Dent fwd of cargo	25/10/2023
101	Damage	FR23 + 10.00mm, STRG24RH + 20.00mm	Dent fwd of cargo door	25/10/2023
102	Damage	FR20 + 20.00mm, STRG30RH + 10.00mm	Lightning strike fwd of avionics door	01/11/2023
103	Damage	FR15 + 10.00mm, STRG22RH + 20.00mm	Lightning strike fwd of service door	02/11/2023
104	Damage	FR23 + 125.00mm, STRG23RH + 59.00mm	Dent on fuse	29/11/2023
106	Damage	FR15 + 100.00mm, STRG19RH + 5.00mm	Dent fwd of pax door 1 rh	04/12/2023


D&B Airlines		DAMAGE CHART A321i EFFECTIVE DATE - 04/06/2025		A/C REG: T-A321C A/C S/N: 0123456	
108	Damage	FR24 + 166.00mm, STRG32RH + 53.00mm	Dent fwd of cargo door	16/01/2024	
110	Damage	FR18 + 98.00mm, STRG23RH + 66.00mm	Dent	07/02/2024	
138	Damage	FR19 + 100.00mm, STRG24RH + 50.00mm	Lightning strike	05/06/2024	

EXAMPLE



Front Top


No	Type	Location	Description	Date
T-174*	Damage	Cockpit Window	Scratch	19/11/2024
T-197*	Damage	FR34 + 90.00mm, STRG12RH + 23.00mm		09/02/2025
T-220*	Damage	FR21 + 112.00mm, STRG11LH + 123.00mm	Dent on fwd fuse	08/04/2025
2	Repair	FR27 + 269.00mm, STRG2RH + 137.00mm	Skin/Fastener Burn on Fuselage - Section 15/21 RH FR26 STRG33	27/04/2015
11	Repair	FR23 + 50.00mm, STRG13LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR23 STRG13	08/09/2017
24	Damage	FR21 + 50.00mm, STRG9LH + 10.00mm	Gouge on Fuselage - Section 15/21 LH FR21 STRG9	27/02/2018
28	Repair	FR25 + 50.00mm, STRG1RH + 10.00mm	Repair on Fuselage - Section 15/21 RH FR25 STRG1	28/02/2018
46	Damage	FR1 + 266.00mm, CLLH + 969.00mm	Dent on Fuselage - Section 15/21 FR1 STRG20	14/01/2022
48	Damage	Cockpit Window	Delamination on Cockpit Window	08/04/2022
50	Damage	Cockpit Window	Delamination on Cockpit Window	08/04/2022
83	Damage	PASSENGER DOOR NO 1 LH	Scratch on PASSENGER DOOR NO 1 LH	25/11/2022
97	Damage	Cockpit Window	Scratches - Flight Deck Captain Sliding Window Inner Panel	26/09/2023



Front Lower


No	Type	Location	Description	Date
T-136*	Damage	FR28 + 178.00mm, STRG27RH + 69.00mm	Dent	02/06/2024
T-143*	Damage	FR21 + 131.00mm, STRG23LH + 60.00mm	Dent aft of pax door 1	09/09/2024
T-148*	Damage	FR28 + 373.00mm, STRG30RH + 61.00mm	2 Dents near CGO door	08/10/2024
T-196*	Damage	FR21 + 145.00mm, STRG24LH + 49.00mm	Dent near pax door	09/02/2025
1	Repair	FR11 + 137.00mm, STRG32RH + 173.00mm	Skin/Fastener Burn on Fuselage - Section 15/21 RH FR10 STRG32	09/01/2012
17	Damage	FR33 + 50.00mm, STRG43RH + 10.00mm	Corrosion on Fuselage - Section 15/21 RH FR33 STRG43	27/03/2018
18	Damage	FR32 + 50.00mm, STRG43LH + 10.00mm	Corrosion on Fuselage - Section 15/21 LH FR32 STRG43	27/03/2018
19	Repair	FR28 + 50.00mm, STRG41RH + 10.00mm	Skin/Fastener Burn on Fuselage - Section 15/21 RH FR28 STRG41	18/03/2018
20	Damage	FR28 + 50.00mm, STRG43LH + 10.00mm	Skin/Fastener Burn on Fuselage - Section 15/21 LH FR28 STRG43	27/03/2018
25	Damage	FR23 + 287.00mm, STRG37LH + 65.00mm	Dent and Gouge on Fuselage - Section 15/21 FR23 STRG37	01/04/2018
44	Damage	FR29 + 50.00mm, STRG27RH + 10.00mm	Dent on Fuselage - Section 15/21 RH FR29 STRG27	20/11/2021
73	Damage	FR34 + 50.00mm, STRG43RH + 10.00mm	Wear Mark on Fuselage - Section 15/21 RH FR34 STRG43	15/11/2022
77	Damage	FR18 + 50.00mm, STRG23LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR18 STRG23	19/11/2022
84	Damage	FR20 + 50.00mm, STRG23LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR20 STRG23	26/11/2022
96	Repair	FR12 + 50.00mm, STRG23LH + 10.00mm	sheared Fateners on Fuselage - Section 11/12 LH FR12 STRG23	08/12/2022

100	Damage	FR23 + 311.00mm, STRG24RH + 52.00mm	Dent fwd of cargo	25/10/2023
101	Damage	FR23 + 10.00mm, STRG24RH + 20.00mm	Dent fwd of cargo door	25/10/2023
102	Damage	FR20 + 20.00mm, STRG30RH + 10.00mm	Lightning strike fwd of avionics door	01/11/2023
108	Damage	FR24 + 166.00mm, STRG32RH + 53.00mm	Dent fwd of cargo door	16/01/2024
110	Damage	FR18 + 98.00mm, STRG23RH + 66.00mm	Dent	07/02/2024
126	Damage	Door - Avionics Compartment Lateral Left	ligghtning strike	17/04/2024
129	Damage	FR19 + 64.00mm, STRG24LH + 53.00mm	Dent below pax door	15/05/2024
138	Damage	FR19 + 100.00mm, STRG24RH + 50.00mm	Lightning strike	05/06/2024
146	Damage	FR24 + 200.00mm, STRG26LH + 70.00mm	Scratch near sensor on lh side	17/09/2024
150	Damage	FR20 + 250.00mm, STRG22LH + 100.00mm	Dent aft of fwd pax door	09/10/2024
175	Damage	FR33 + 59.00mm, STRG23LH + 91.00mm	Dents near middle pax door	02/12/2024
192	Damage	FR23 + 50.00mm, STRG29LH + 20.00mm	Dent near aoa probe	17/12/2024
193	Damage	FR24 + 50.00mm, STRG28LH + 10.00mm	Strike near aoa probe	17/12/2024
194	Damage	FR25 + 180.00mm, STRG24LH + 70.00mm	Dents below aoa sensor	21/01/2025
215	Damage	FR19 + 100.00mm, STRG24LH + 40.00mm	Dent below fwd pax door	04/03/2025
216	Damage	FR17 + 120.00mm, STRG24LH + 90.00mm	Dent below fwd pax door	05/03/2025
227	Damage	FR17 + 150.00mm, STRG24LH + 100.00mm	Dent below fwd pax door	15/04/2025
229	Damage	FR26 + 10.00mm, STRG24LH - 10.00mm	Dent	12/05/2025




Mid LH

No	Type	Location	Description	Date
56	Damage	FR45 + 50.00mm, STRG23LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR45 STRG23	20/10/2022
57	Damage	FR47 + 50.00mm, STRG23LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR47 STRG23	29/10/2022
58	Damage	FR46 + 104.00mm, STRG18LH + 9.00mm	Corrosion on Fuselage - Section 11/12 LH FR47 STRG23	30/10/2022




Mid RH

No	Type	Location	Description	Date
T-105*	Damage	FR35 + 413.00mm, STRG22RH + 61.00mm	Dent fwd rh door no 2	03/12/2023




Mid Top

No	Type	Location	Description	Date
±	Damage			




Mid Lower

No	Type	Location	Description	Date
±	Damage			




Aft LH

No	Type	Location	Description	Date
16	Damage	FR85 + 50.00mm, STRG17LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR85 STRG17	27/02/2018
31	Damage	FR68 + 50.00mm, STRG18LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR68 STRG18	31/03/2018
35	Damage	FR69 + 50.00mm, STRG19LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR69 STRG19	23/08/2021
40	Damage	FR68 + 50.00mm, STRG21LH + 10.00mm	Scratch on Fuselage - Section 15/21 LH FR68 STRG21	23/08/2021
70	Damage	FR85 + 228.00mm, STRG17LH + 6.00mm	Dent on Fuselage - Section 15/21 LH FR85 STRG16	12/11/2022
71	Damage	FR85 + 245.00mm, STRG17LH + 18.00mm	Dent on Horizontal Stabilizer Leading Edge RH	13/11/2022
79	Damage	FR67 + 204.00mm, STRG24LH + 90.00mm	Corrosion on Fuselage L2 Door Sill - Section 11/12 LH FR67 STRG24	21/11/2022



Aft RH

No	Type	Location	Description	Date
T-99*	Repair	FR59 + 94.00mm, STRG19RH + 93.00mm	Dent - Fuse. Skin, FR59, S19R-S20R	26/09/2023
7	Damage	FR70 + 227.00mm, STRG31RH + 85.00mm	Corrosion on Fuselage - Section 15/21 RH FR69 STRG30	07/07/2016
8	Damage	FR84 + 50.00mm, STRG19RH + 10.00mm	Dent on Fuselage - Section 15/21 RH FR84 STRG19	01/04/2017
9	Damage	FR84 + 50.00mm, STRG19RH + 10.00mm	Dent on Fuselage - Section 15/21 RH FR84 STRG19	01/04/2017
10	Damage	FR71 + 11.00mm, STRG27RH + 20.00mm	Dent on Fuselage - Section 15/21 RH FR71 STRG27	03/04/2017
69	Damage	FR66 + 42.00mm, STRG24RH + 6.00mm	Corrosion on Fuselage - Section 11/12 RH FR66 STRG23	11/11/2022
72	Damage	FR53 + 263.00mm, STRG39RH + 58.00mm	Corrosion on Fuselage - Section 11/12 RH FR53 STRG38	14/11/2022
74	Damage	FR49 + 200.00mm, STRG27RH + 60.00mm	Crack on Wing-to-Body Fairing RH FR49 STRG27	16/11/2022
78	Damage	FR67 + 138.00mm, STRG24RH + 86.00mm	Corrosion on Fuselage R2 Door Sill - Section 11/12 RH FR67 STRG24	20/11/2022
80	Damage	FR60 + 50.00mm, STRG38RH + 10.00mm	Corrosion on Fuselage Bulk Cargo Door Sill- Section 11/12 RH FR60 STRG38	22/11/2022
82	Damage	FR66 + 120.00mm, STRG24RH + 49.00mm	Corrosion on Fuselage R2 Door Sill - Section 11/12 RH FR66 STRG23	24/11/2022
92	Damage	AFT CARGO DOOR - 826	Corrosion on Aft Cargo Door	04/12/2022
93	Damage	FR67 + 468.00mm, STRG24RH + 103.00mm	Corrosion on Fuselage - Section 11/12 RH FR67 STRG24	05/12/2022




Aft Top

No	Type	Location	Description	Date
7	Damage	FR70 + 227.00mm, STRG31RH + 85.00mm	Corrosion on Fuselage - Section 15/21 RH FR69 STRG30	07/07/2016
10	Damage	FR71 + 11.00mm, STRG27RH + 20.00mm	Dent on Fuselage - Section 15/21 RH FR71 STRG27	03/04/2017
16	Damage	FR85 + 50.00mm, STRG17LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR85 STRG17	27/02/2018
47	Damage	ANTENNA RADIO ALTIMETER - 5SA1	Marking Missing on ANTENNA RADIO ALTIMETER - 5SA1	15/01/2022
69	Damage	FR66 + 42.00mm, STRG24RH + 6.00mm	Corrosion on Fuselage - Section 11/12 RH FR66 STRG23	11/11/2022
72	Damage	FR53 + 263.00mm, STRG39RH + 58.00mm	Corrosion on Fuselage - Section 11/12 RH FR53 STRG38	14/11/2022
74	Damage	FR49 + 200.00mm, STRG27RH + 60.00mm	Crack on Wing-to-Body Fairing RH FR49 STRG27	16/11/2022
75	Damage	FR51 + 335.00mm, STRG39LH + 61.00mm	Crack on Wing-to-Body Fairing LH FR51 STRG39	17/11/2022
78	Damage	FR67 + 138.00mm, STRG24RH + 86.00mm	Corrosion on Fuselage R2 Door Sill - Section 11/12 RH FR67 STRG24	20/11/2022
79	Damage	FR67 + 204.00mm, STRG24LH + 90.00mm	Corrosion on Fuselage L2 Door Sill - Section 11/12 LH FR67 STRG24	21/11/2022
80	Damage	FR60 + 50.00mm, STRG38RH + 10.00mm	Corrosion on Fuselage Bulk Cargo Door Sill- Section 11/12 RH FR60 STRG38	22/11/2022
82	Damage	FR66 + 120.00mm, STRG24RH + 49.00mm	Corrosion on Fuselage R2 Door Sill - Section 11/12 RH FR66 STRG23	24/11/2022
90	Damage	FR58 + 50.00mm, STRG43LH + 10.00mm	Corrosion on Fuselage - Section 15/21 LH FR58 STRG43	02/12/2022
92	Damage	AFT CARGO DOOR - 826	Corrosion on Aft Cargo Door	04/12/2022
93	Damage	FR67 + 468.00mm, STRG24RH + 103.00mm	Corrosion on Fuselage - Section 11/12 RH FR67 STRG24	05/12/2022


	DAMAGE CHART A321i EFFECTIVE DATE - 04/06/2025	A/C REG: T-A321C A/C S/N: 0123456 
---	---	--

EXAMPLE




Aft Lower

No	Type	Location	Description	Date
16	Damage	FR85 + 50.00mm, STRG17LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR85 STRG17	27/02/2018
70	Damage	FR85 + 228.00mm, STRG17LH + 6.00mm	Dent on Fuselage - Section 15/21 LH FR85 STRG16	12/11/2022
71	Damage	FR85 + 245.00mm, STRG17LH + 18.00mm	Dent on Horizontal Stabilizer Leading Edge RH	13/11/2022



Cockpit Windows LH


No	Type	Location	Description	Date
T-174*	Damage	Cockpit Window	Scratch	19/11/2024
T-177*	Damage	RADOME-NOSE - 1560WM		10/12/2024
38	Damage	Cockpit Window	Gas Bubble on Cockpit Window	06/12/2020
46	Damage	FR1 + 266.00mm, CLLH + 969.00mm	Dent on Fuselage - Section 15/21 FR1 STRG20	14/01/2022
48	Damage	Cockpit Window	Delamination on Cockpit Window	08/04/2022
49	Damage	Cockpit Window	Delamination on Cockpit Window	08/04/2022
50	Damage	Cockpit Window	Delamination on Cockpit Window	08/04/2022
51	Damage	Cockpit Window	Delamination on Cockpit Window	15/10/2022
52	Damage	Cockpit Window	Scratch on Cockpit Window	16/10/2022
53	Damage	Cockpit Window	Delamination on Cockpit Window	17/10/2022
54	Damage	Cockpit Window	Discoloration on Cockpit Window	18/10/2022
96	Repair	FR12 + 50.00mm, STRG23LH + 10.00mm	sheared Fasteners on Fuselage - Section 11/12 LH FR12 STRG23	08/12/2022
97	Damage	Cockpit Window	Scratches - Flight Deck Captain Sliding Window Inner Panel	26/09/2023



Cockpit Windows RH


No	Type	Location	Description	Date
T-177*	Damage	RADOME-NOSE - 1560WM		10/12/2024
38	Damage	Cockpit Window	Gas Bubble on Cockpit Window	06/12/2020
48	Damage	Cockpit Window	Delamination on Cockpit Window	08/04/2022
49	Damage	Cockpit Window	Delamination on Cockpit Window	08/04/2022
50	Damage	Cockpit Window	Delamination on Cockpit Window	08/04/2022
51	Damage	Cockpit Window	Delamination on Cockpit Window	15/10/2022
52	Damage	Cockpit Window	Scratch on Cockpit Window	16/10/2022
97	Damage	Cockpit Window	Scratches - Flight Deck Captain Sliding Window Inner Panel	26/09/2023

Wings




LH Top

No	Type	Location	Description	Date
T-140*	Damage	COWL ASSY-AIR INLET - 1100KM1	Ligntning strike 3 entry points	13/06/2024
23	Damage	Wing LH B	Corrosion on Wing LH 1	11/03/2018
33	Damage	Cowl Assy 2 Inboard LH	Skin/Fastener Burn on Cowl Assy 2 Inboard LH	12/03/2019
39	Damage	Outboard Flap 1 LH	Dent on Inboard Flap 1 LH	23/08/2021
42	Damage	Cowl Assy 2 Inboard LH	Dent on COWL ASSY-AIR INLET - 1100KM1	10/03/2018
88	Damage	Wing LH B	Corrosion on Wing LH 1	30/11/2022




RH Top

No	Type	Location	Description	Date
6	Damage	Winglet RH	Skin/Fastener Burn on Wing RH 1	06/07/2016
12	Repair	Winglet RH	Skin/Fastener Burn on Wing RH 1	27/03/2018
68	Damage	PYLON AFT FIXED FAIRING RH - 001	Chafing on PYLON AFT FIXED FAIRING RH - 001	10/11/2022
74	Damage	FR49 + 200.00mm, STRG27RH + 60.00mm	Crack on Wing-to-Body Fairing RH FR49 STRG27	16/11/2022



RH Lower


No	Type	Location	Description	Date
3	Damage	Inboard Flap 1 RH	Dent on Inboard Flap 1 RH	27/04/2015
12	Repair	Winglet RH	Skin/Fastener Burn on Wing RH 1	27/03/2018
13	Damage	Inboard Flap 1 RH	Dent on Inboard Flap 1 RH	27/03/2018
27	Damage	Inboard Flap 1 RH	Dent on LH INBOARD FLAP LOWER SURFACE	01/04/2018
60	Damage	Outboard Flap 1 RH	Chafing on Outboard Flap 1 RH	01/11/2022



LH Lower


No	Type	Location	Description	Date
5	Damage	Inboard Flap 1 LH	Dent on Inboard Flap 1 LH	06/07/2016
33	Damage	Cowl Assy 2 Inboard LH	Skin/Fastener Burn on Cowl Assy 2 Inboard LH	12/03/2019
39	Damage	Outboard Flap 1 LH	Dent on Inboard Flap 1 LH	23/08/2021
42	Damage	Cowl Assy 2 Inboard LH	Dent on COWL ASSY-AIR INLET - 1100KM1	10/03/2018
59	Damage	Outboard Flap 1 LH	Chafing on Outboard Flap 1 LH	31/10/2022
61	Damage	Wing LH A	Corrosion on Wing LH 1	02/11/2022

Stabilisers




Vert Stab. LH

No	Type	Location	Description	Date
6	Damage	Winglet RH	Skin/Fastener Burn on Wing RH 1	06/07/2016
16	Damage	FR85 + 50.00mm, STRG17LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR85 STRG17	27/02/2018
26	Damage	VERT. STABILIZER RUDDER - 326	Skin/Fastener Burn on VERT. STABILIZER RUDDER - 326	18/03/2018
30	Damage	Horizontal Stabilizer Leading Edge LH	Dent on Horizontal Stabilizer Leading Edge LH	02/04/2018
31	Damage	FR68 + 50.00mm, STRG18LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR68 STRG18	31/03/2018
35	Damage	FR69 + 50.00mm, STRG19LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR69 STRG19	23/08/2021
40	Damage	FR68 + 50.00mm, STRG21LH + 10.00mm	Scratch on Fuselage - Section 15/21 LH FR68 STRG21	23/08/2021
45	Damage	Horizontal Stabilizer Leading Edge LH	Dent on Horizontal Stabilizer Leading Edge LH	21/11/2021
70	Damage	FR85 + 228.00mm, STRG17LH + 6.00mm	Dent on Fuselage - Section 15/21 LH FR85 STRG16	12/11/2022
71	Damage	FR85 + 245.00mm, STRG17LH + 18.00mm	Dent on Horizontal Stabilizer Leading Edge RH	13/11/2022
79	Damage	FR67 + 204.00mm, STRG24LH + 90.00mm	Corrosion on Fuselage L2 Door Sill - Section 11/12 LH FR67 STRG24	21/11/2022




Vert Stab. RH

No	Type	Location	Description	Date
7	Damage	FR70 + 227.00mm, STRG31RH + 85.00mm	Corrosion on Fuselage - Section 15/21 RH FR69 STRG30	07/07/2016
8	Damage	FR84 + 50.00mm, STRG19RH + 10.00mm	Dent on Fuselage - Section 15/21 RH FR84 STRG19	01/04/2017
9	Damage	FR84 + 50.00mm, STRG19RH + 10.00mm	Dent on Fuselage - Section 15/21 RH FR84 STRG19	01/04/2017
10	Damage	FR71 + 11.00mm, STRG27RH + 20.00mm	Dent on Fuselage - Section 15/21 RH FR71 STRG27	03/04/2017
26	Damage	VERT. STABILIZER RUDDER - 326	Skin/Fastener Burn on VERT. STABILIZER RUDDER - 326	18/03/2018
69	Damage	FR66 + 42.00mm, STRG24RH + 6.00mm	Corrosion on Fuselage - Section 11/12 RH FR66 STRG23	11/11/2022
78	Damage	FR67 + 138.00mm, STRG24RH + 86.00mm	Corrosion on Fuselage R2 Door Sill - Section 11/12 RH FR67 STRG24	20/11/2022
82	Damage	FR66 + 120.00mm, STRG24RH + 49.00mm	Corrosion on Fuselage R2 Door Sill - Section 11/12 RH FR66 STRG23	24/11/2022
93	Damage	FR67 + 468.00mm, STRG24RH + 103.00mm	Corrosion on Fuselage - Section 11/12 RH FR67 STRG24	05/12/2022



Horiz Stab. Top


No	Type	Location	Description	Date
30	Damage	Horizontal Stabilizer Leading Edge LH	Dent on Horizontal Stabilizer Leading Edge LH	02/04/2018
31	Damage	FR68 + 50.00mm, STRG18LH + 10.00mm	Dent on Fuselage - Section 15/21 LH FR68 STRG18	31/03/2018
45	Damage	Horizontal Stabilizer Leading Edge LH	Dent on Horizontal Stabilizer Leading Edge LH	21/11/2021



Horiz Stab. Lower


No	Type	Location	Description	Date
10	Damage	FR71 + 11.00mm, STRG27RH + 20.00mm	Dent on Fuselage - Section 15/21 RH FR71 STRG27	03/04/2017

#1 Engine




#1 Front

No	Type	Location	Description	Date
T-125*	Damage	Fan Blade 2 LH	Nick on blade 2 no 1 eng	16/04/2024
T-153*	Repair	Fan Blade 11 LH	Nick on lh 11	22/10/2024
T-168*	Damage	Fan Blade 31 LH		23/10/2024
29	Damage	COWL ASSY-AIR INLET - 1100KM1	Dent on COWL ASSY-AIR INLET - 1100KM1	31/03/2018
86	Damage	COWL ASSY-AIR INLET - 1100KM1	Abrasion on Attrition Lining - 1100KM1	28/11/2022
122	Damage	COWL ASSY-AIR INLET - 1100KM1	Dent on cowl lip	16/04/2024




#1 Rear

No	Type	Location	Description	Date
33	Damage	Cowl Assy 2 Inboard LH	Skin/Fastener Burn on Cowl Assy 2 Inboard LH	12/03/2019




#1 LH Side

No	Type	Location	Description	Date
T-140*	Damage	COWL ASSY-AIR INLET - 1100KM1	Ligntning strike 3 entry points	13/06/2024
33	Damage	Cowl Assy 2 Inboard LH	Skin/Fastener Burn on Cowl Assy 2 Inboard LH	12/03/2019
42	Damage	Cowl Assy 2 Inboard LH	Dent on COWL ASSY-AIR INLET - 1100KM1	10/03/2018
122	Damage	COWL ASSY-AIR INLET - 1100KM1	Dent on cowl lip	16/04/2024




#1 RH Side

No	Type	Location	Description	Date
34	Damage	Cowl Assy 1 Inboard LH	Skin/Fastener Burn on Cowl Assy 1 Inboard LH	13/03/2019
36	Damage	COWL ASSY-AIR INLET - 1100KM1	Damage on Cowl Assy 1 Inboard LH	13/08/2019
41	Repair	COWL ASSY-AIR INLET - 1100KM1	Repair on COWL ASSY-AIR INLET - 1100KM1	19/10/2021



#1 Top


No	Type	Location	Description	Date
±	Damage			



#1 Lower


No	Type	Location	Description	Date
33	Damage	Cowl Assy 2 Inboard LH	Skin/Fastener Burn on Cowl Assy 2 Inboard LH	12/03/2019
34	Damage	Cowl Assy 1 Inboard LH	Skin/Fastener Burn on Cowl Assy 1 Inboard LH	13/03/2019

#2 Engine




#2 Front

No	Type	Location	Description	Date
4	Repair	COWL ASSY-AIR INLET - 1100KM2	Dent on COWL ASSY-AIR INLET - 1100KM2	29/06/2017
14	Damage	COWL ASSY-AIR INLET - 1100KM2	Dent on Cowl Assy 2 Inboard RH	28/03/2018
37	Damage	COWL ASSY-AIR INLET - 1100KM2	Dent on COWL ASSY-AIR INLET - 1100KM2	24/04/2020
81	Damage	COWL ASSY-AIR INLET - 1100KM2	Dent on COWL ASSY-AIR INLET - 1100KM2	23/11/2022
85	Damage	Fan Blade 1 RH	Pitting on Fan Blade 1 RH	27/11/2022
87	Damage	COWL ASSY-AIR INLET - 1100KM2	Scratch on COWL ASSY-AIR INLET - 1100KM2	29/11/2022
91	Damage	COWL ASSY-AIR INLET - 1100KM2	Scratch on COWL ASSY-AIR INLET - 1100KM2	03/12/2022




#2 Rear

No	Type	Location	Description	Date
±	Damage			




#2 RH Side

No	Type	Location	Description	Date
4	Repair	COWL ASSY-AIR INLET - 1100KM2	Dent on COWL ASSY-AIR INLET - 1100KM2	29/06/2017
37	Damage	COWL ASSY-AIR INLET - 1100KM2	Dent on COWL ASSY-AIR INLET - 1100KM2	24/04/2020
81	Damage	COWL ASSY-AIR INLET - 1100KM2	Dent on COWL ASSY-AIR INLET - 1100KM2	23/11/2022
89	Damage	COWL ASSY-AIR INLET - 1100KM2	Scratch on COWL ASSY-AIR INLET - 1100KM2	01/12/2022




#2 LH Side

No	Type	Location	Description	Date
±	Damage			



#2 Top


No	Type	Location	Description	Date
89	Damage	COWL ASSY-AIR INLET - 1100KM2	Scratch on COWL ASSY-AIR INLET - 1100KM2	01/12/2022



#2 Lower


No	Type	Location	Description	Date
±	Damage			

Floors




Fwd Cargo Floor

No	Type	Location	Description	Date
67	Damage	FR33 + 50.00mm, STRG39LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR33 STRG39	09/11/2022
94	Damage	FR33 + 50.00mm, STRG39RH + 10.00mm	Corrosion on Fuselage - Section 11/12 RH FR33 STRG39	06/12/2022




Aft Cargo Floor

No	Type	Location	Description	Date
62	Damage	FR61 + 50.00mm, STRG40LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR61 STRG40	03/11/2022
63	Damage	FR60 + 50.00mm, STRG42RH + 10.00mm	Corrosion on Fuselage - Section 11/12 RH FR60 STRG42	04/11/2022
64	Damage	FR55 + 50.00mm, STRG43LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR55 STRG43	05/11/2022
65	Damage	FR56 + 50.00mm, STRG44LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR56 STRG44	06/11/2022
66	Damage	FR57 + 50.00mm, STRG42LH + 10.00mm	Corrosion on Fuselage - Section 11/12 LH FR57 STRG42	07/11/2022




Fwd Cabin Floor

No	Type	Location	Description	Date
T-165*	Damage	Passenger Floor Panel 39	Corrosion	23/10/2024



Centre Cabin Floor


No	Type	Location	Description	Date
±	Damage			




Aft Cabin Floor

No	Type	Location	Description	Date
±	Damage			

Cargo doors



No	Type	Location	Description	Date
T-98*	Damage	FR23 + 280.00mm, STRG18RH + 55.00mm	Dent - Fuse Skin, AFT of R1 Door, FWD of Triangle Reference Point, FR 23 -24, S18R-S19R	26/09/2023
T-136*	Damage	FR28 + 178.00mm, STRG27RH + 69.00mm	Dent	02/06/2024
T-148*	Damage	FR28 + 373.00mm, STRG30RH + 61.00mm	2 Dents near CGO door	08/10/2024
19	Repair	FR28 + 50.00mm, STRG41RH + 10.00mm	Skin/Fastener Burn on Fuselage - Section 15/21 RH FR28 STRG41	18/03/2018
44	Damage	FR29 + 50.00mm, STRG27RH + 10.00mm	Dent on Fuselage - Section 15/21 RH FR29 STRG27	20/11/2021
100	Damage	FR23 + 311.00mm, STRG24RH + 52.00mm	Dent fwd of cargo	25/10/2023
101	Damage	FR23 + 10.00mm, STRG24RH + 20.00mm	Dent fwd of cargo door	25/10/2023
102	Damage	FR20 + 20.00mm, STRG30RH + 10.00mm	Lightning strike fwd of avionics door	01/11/2023
104	Damage	FR23 + 125.00mm, STRG23RH + 59.00mm	Dent on fuse	29/11/2023
108	Damage	FR24 + 166.00mm, STRG32RH + 53.00mm	Dent fwd of cargo door	16/01/2024
110	Damage	FR18 + 98.00mm, STRG23RH + 66.00mm	Dent	07/02/2024
138	Damage	FR19 + 100.00mm, STRG24RH + 50.00mm	Lightning strike	05/06/2024



No	Type	Location	Description	Date
T-99*	Repair	FR59 + 94.00mm, STRG19RH + 93.00mm	Dent - Fuse. Skin, FR59, S19R-S20R	26/09/2023
47	Damage	ANTENNA RADIO ALTIMETER - 5SA1	Marking Missing on ANTENNA RADIO ALTIMETER - 5SA1	15/01/2022
61	Damage	Wing LH A	Corrosion on Wing LH 1	02/11/2022
72	Damage	FR53 + 263.00mm, STRG39RH + 58.00mm	Corrosion on Fuselage - Section 11/12 RH FR53 STRG38	14/11/2022
80	Damage	FR60 + 50.00mm, STRG38RH + 10.00mm	Corrosion on Fuselage Bulk Cargo Door Sill- Section 11/12 RH FR60 STRG38	22/11/2022
90	Damage	FR58 + 50.00mm, STRG43LH + 10.00mm	Corrosion on Fuselage - Section 15/21 LH FR58 STRG43	02/12/2022
92	Damage	AFT CARGO DOOR - 826	Corrosion on Aft Cargo Door	04/12/2022